

	National Aeronautical Laboratory	Documentation Sheet	Document Classification Restricted
Title	: Damage to the Propeller Blades of HPT-32 Aircraft X-2518		Document No. PD MT 8660 Date of issue: Dec. '86
Author(s)	: A.C.Raghuram, S.Radhakrishnan, R.V.Krishnan & V.Ramachandran		Contents 6 pages incl. 6 figures
Division	: Materials Science		No. of copies: 12
External participation			NAL Project No. MT-9-861, MT-1-167
Sponsor	: Aeronautics R & D Board		Sponsor's Project No. Aero/RD-134/100/10/
Approval	: A.C.Raghuram		84-85/394
Remarks	:		
Keywords	: HPT-32 aircraft, Propeller blades, Impact failure, Rearward bending, Engine idling		
Abstract	: <p style="text-align: center;"> A HPT-32 aircraft was involved in an accident during an engine idling exercise. The aircraft was powered by a twin blade propeller engine. The blades had bent backwards. One of the blades had fractured at a location one third from the tip. The blade pitch angle was at the fine pitch stop. The rearward bending of the blades and the fine pitch of the blade angle indicate propeller rotation at the time of impact, with low or no power. It was learnt that the engine had problems of cutting off at idling speed on several occasions in the past. As the sortie involved an engine idling exercise, it could well be possible that it had cut off. </p>		